



2009 UKGSer Events: Gathering of the Clans (Scotland) 5th - 7th June 2009.

Click Here To Subscribe	Get Latest Posts ▾	My Posts ▾	Useful Links	Merchandise	GSers Photos
UKGSer.com > Technical & Rider > 650 & 450 singles					Welcome, WayneC. You last visited: Yesterday at 23:14
650 fork failure					
User CP	Register	FAQ	Members List	Calendar	Search ▾ Quick Links ▾ Log Out

650 & 450 singles Single cylinder chain drive talk

[post reply](#) Page 2 of 2 < 1 2 ▾

[Thread Tools](#) ▾ [Search this Thread](#) ▾ [Display Modes](#) ▾

22-03-09, 07:58 #17

talltony

Subscriber
Subscribed
Tosser



Join Date: Mar 2005
Location: Dorset, UK
Posts: 304

Assuming that the replacement is post '03 it'll be the later type slider and you'll be fine.

Tony



28-05-09, 21:10 #18

talltony

Subscriber
Subscribed
Tosser



Join Date: Mar 2005
Location: Dorset, UK
Posts: 304

Official investigation started.

The US National Highway Traffic Safety Administration has started an investigation into these fork failures.

Safety Ratings	Defects & Recalls	Safe Driving Information	Resources
----------------	-------------------	--------------------------	-----------

DEFECTS & RECALLS

Office of Defects Investigation (ODI)

Safety Complaints 2

File a Complaint
online or by phone
Search Complaints

Defect Investigations

Safety Recalls

Service Bulletins

Downloads

Foreign Campaigns

EWR Information

Sitemap

Contact ODI
(888) 327-4236
TTY: (800) 424-9153

DEFECT INVESTIGATIONS - SEARCH RESULTS

Navigate: [ODI Home](#) » [Defect Investigations](#) » Results List Help

Search Results

Report Date : **May 27, 2009 at 03:03 PM**

NHTSA Action Number : **PE09026**

NHTSA Action Number : PE09026

Make / Models :
BMW / F650 GS
BMW / F650GS
BMW / F650GS DAKAR

Manufacturer : BMW OF NORTH AMERICA, LLC
Component : SUSPENSION:FRONT
Date Investigation Opened : May 18, 2009
Date Investigation Closed : Open

Summary:
BETWEEN AUGUST 15 AND DECEMBER 26, 2008, ODI RECEIVED FIVE VEHICLE OWNER QUESTIONNAIRES ALLEGING PARTIAL OR FULL FRONT WHEEL SEPARATION WHEN THE FORK'S AXLE RETAINING LUG FAILED. TO LEARN MORE ABOUT THIS SUBJECT, AND BMW'S RESPONSE TO IT, WE ARE OPENING THIS PE.

Check to Request Research. Submit below.

NHTSA Recall Campaign Number : N/A

Model/Build Years:
2003
2001-2002
2001-2002

RSS | Web Policies & Notices | Terms of Use | FOIA | Privacy Policy | Cookie Policy | Accessibility | E-mail NHTSA



Documents may be submitted to:

Office of Defect Investigations

National Highway Traffic Safety Administration

1200 New Jersey Ave SE

Washington DC 20590

USA

Attn: Bob Young, Principal Investigator, PE09-026

Please submit only factual information which is relevant to this problem.
(spamming the guy with rants about BMW, or your own "expert opinion" on this issue will probably not help much.)
Accidents need not occur within the United States to be reported.

Tony



Page 2 of 2 < 1 2 >

Quick Reply

Message:



Please click one of the Quick Reply icons in the posts above to activate Quick Reply.

Options

Quote message in reply?

Post Quick Reply

Go Advanced

Posting Rules

You **may** post new threads
You **may** post replies
You **may not** post attachments
You **may** edit your posts

vB code is **On**
Smilies are **On**
[IMG] code is **On**
HTML code is **On**

Forum Jump

650 & 450 singles

Go

All times are GMT +10. The time now is 00:30.

-- :: UKGS'er.com :: Yellow

Contact Us - <http://www.ukgser.com> - [Archive](#) - [Top](#)

Anyone attending a Ride Out or Event organised through the UKGSer Forums does so at their own risk. UKGSer.com or anyone organising an event posted here will not be held responsible in any way for damage or personal injury sustained while attending any such events.
Members attending any such event do so at their own risk.

The text, images, graphics, sound files, animation files, video files, and their arrangement on this Website are all subject to copyright and other intellectual property protection. These objects may not be copied for commercial use or distribution, nor may these objects be modified or reposted to other sites without prior written permission.

Disclaimer: Use or depiction of the BMW logo or trademark throughout this web site is for illustrative and editorial purposes only, and to the benefit of the trademark owner, with no intention of infringement of the trademark.

The UKGSer Forums may include adult content for which it cannot be held responsible. Your use of this website constitutes acceptance of the UKGSER network [privacy policy](#)

"Its about being a grown up hooligan - and if that means a dark visor, remus open pipe and a bit of speeding out of town then all well and good"

Powered by vBulletin® Version 3.6.8
Copyright ©2000 - 2009, Jelsoft Enterprises Ltd.