



- Home
- Vehicle Shoppers
- Vehicle Owners
- Vehicle Manufacturers
- About NHTSA

File a Complaint

Search Complaints

Safety Recalls

Defect Investigations

Service Bulletins

Resources

Frequently Asked Questions
Get answers to the most frequently asked questions about Safety Ratings

DEFECTS & RECALLS

COMPLAINTS - SEARCH RESULTS

You are here: [Home](#) / [Vehicle Owners](#) / [Search Complaints](#) / [Search Complaints](#) / Results List

Help

Search Results

Report Date : **October 30, 2010 at 01:16 AM** New Search

ODI Numbers Searched: **10238415** Print Version

Results : **3** | All records displayed

Make : BMW **Model :** F650GS **Year :** 2002

Manufacturer : BMW OF NORTH AMERICA, LLC

Crash : Yes **Fire :** No **Number of Injuries:** 1

ODI ID Number : 10238415 **Number of Deaths:** 0

Date of Failure: August 2, 2008

VIN : WB10182A42Z...

Component: STEERING

Summary:

TL*THE CONTACT OWNS A 2002 BMW F650GS. WHILE RIDING AT 65 MPH, THE MOTORCYCLE, WOBBLLED, AND PROCEEDED TO THROW THE CONTACT FROM SIDE TO SIDE. THE HANDLE BARS DISCONNECTED AND NO LONGER CONTROLLED THE STEERING. THE CONTACT WAS THROWN FROM THE MOTORCYCLE. THERE WAS NO IMPACT, BUT THE VEHICLE SLID ACROSS THE ASPHALT AND THE ENTIRE FRONT WHEEL DETACHED FROM THE VEHICLE. THE CONTACT SUSTAINED FRACTURES TO HER LEFT FOREARM AND HAND. A POLICE REPORT WAS FILED. SHE WAS AIRLIFTED TO THE HOSPITAL. THE FAILURE MILEAGE WAS APPROXIMATELY 30,000. UPDATED 10/28/08 *BF UPDATED 10/30/08. *JB

Document Search

Check to Request Research. Submit below.

Make : BMW **Model :** F650GS **Year :** 2002

Manufacturer : BMW OF NORTH AMERICA, LLC

Crash : Yes **Fire :** No **Number of Injuries:** 1

ODI ID Number : 10238415 **Number of Deaths:** 0

Date of Failure: August 2, 2008

VIN : WB10182A42Z...

Component: SUSPENSION:FRONT

Summary:

TL*THE CONTACT OWNS A 2002 BMW F650GS. WHILE RIDING AT 65 MPH, THE MOTORCYCLE, WOBBLLED, AND PROCEEDED TO THROW THE CONTACT FROM SIDE TO SIDE. THE HANDLE BARS DISCONNECTED AND NO LONGER CONTROLLED THE STEERING. THE CONTACT WAS THROWN FROM THE MOTORCYCLE. THERE WAS NO IMPACT, BUT THE VEHICLE SLID ACROSS THE ASPHALT AND THE ENTIRE FRONT WHEEL DETACHED FROM THE VEHICLE. THE CONTACT SUSTAINED FRACTURES TO HER LEFT FOREARM AND HAND. A POLICE REPORT WAS FILED. SHE WAS AIRLIFTED TO THE HOSPITAL. THE FAILURE MILEAGE WAS APPROXIMATELY 30,000. UPDATED 10/28/08 *BF UPDATED 10/30/08. *JB

Document Search

Check to Request Research. Submit below.

Make : BMW **Model :** F650GS **Year :** 2002

Manufacturer : BMW OF NORTH AMERICA, LLC

Crash : Yes **Fire :** No **Number of Injuries:** 1

ODI ID Number : 10238415**Number of Deaths:** 0**Date of Failure:** August 2, 2008**VIN :** WB10182A42Z...**Component:** WHEELS**Summary:**

TL*THE CONTACT OWNS A 2002 BMW F650GS. WHILE RIDING AT 65 MPH, THE MOTORCYCLE, WOBBLED, AND PROCEEDED TO THROW THE CONTACT FROM SIDE TO SIDE. THE HANDLE BARS DISCONNECTED AND NO LONGER CONTROLLED THE STEERING. THE CONTACT WAS THROWN FROM THE MOTORCYCLE. THERE WAS NO IMPACT, BUT THE VEHICLE SLID ACROSS THE ASPHALT AND THE ENTIRE FRONT WHEEL DETACHED FROM THE VEHICLE. THE CONTACT SUSTAINED FRACTURES TO HER LEFT FOREARM AND HAND. A POLICE REPORT WAS FILED. SHE WAS AIRLIFTED TO THE HOSPITAL. THE FAILURE MILEAGE WAS APPROXIMATELY 30,000. UPDATED 10/28/08 *BF UPDATED 10/30/08. *JB

[Document Search](#) Check to Request Research. Submit below.[Request Research](#)NHTSA.GOV | STOPIMPAIREDDRIVING.ORG | TRAFFICSAFETYMARKETING

[Policies](#) | [Terms of Use](#) | [USA.gov](#) | [FOIA](#) | [Privacy Policy](#) | [Accessibility](#) | [Careers](#) | [Site Map](#) | [Contact NHTSA](#)
1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA 1.888.327.4236 TTY 1.800.424.9153

