



OFFICE OF DEFECTS INVESTIGATION (ODI)

Complaints - Search Results

2 Record(s) Displayed.

Report Date: October 20, 2008 at 08:53 PM

ODI Numbers Searched: 10245369

Make: BMW **Model**: F650 CS **Year**: 2003

Manufacturer: BAYERISCHE MOTOREN WERKE

 Crash : Yes
 Fire : No
 Number of Injuries: 1

 ODI ID Number : 10245369
 Number of Deaths: 0

Date of Failure: September 2, 2008

VIN: WB10183A33Z...

Component: SUSPENSION:FRONT

Summary:

I WAS ON A MOTORCYCLE TRIP TO BANFF, AB. ABOUT 50K NORTH OF CROWSNEST PASS, AB ON GRAVEL HIGHWAY 40 I HAD A BIT OF A WOBBLE THAT MOVED ME INTO THE SOFT GRAVEL SHOULDER. IT WAS SAFER TO RIDE INTO THE DITCH SO THAT IS WHAT I DID. JUST AFTER COMING UP ON THE OTHER SIDE OF THE DITCH THE FRONT FORK BROKE ON A SMALL BUMP LAUNCHING ME THROUGH THE AIR, AND TOPPLING THE BIKE BEHIND ME. I WAS PROBABLY GOING ABOUT 40MPH AT THE TIME OF THE FAILURE. I DISLOCATED MY SHOULDER AND TORE SEVERAL TENDONS IN THE INCIDENT. THE MOTORCYCLE IS A BMW F650 GS DAKAR. THE FAILURE IS VERY SIMILAR TO... CASE: IVOQ-2002 BMW MOTORCYCLE CASE NUMBER: 28597. *TR

 Make:
 BMW
 Model:
 F650 CS
 Year:
 2003

Manufacturer: BAYERISCHE MOTOREN WERKE

Crash : YesFire : NoNumber of Injuries: 1ODI ID Number : 10245369Number of Deaths: 0

Date of Failure: September 2, 2008

VIN: WB10183A33Z...

Component: WHEELS

Summary:

I WAS ON A MOTORCYCLE TRIP TO BANFF, AB. ABOUT 50K NORTH OF CROWSNEST PASS, AB ON GRAVEL HIGHWAY 40 I HAD A BIT OF A WOBBLE THAT MOVED ME INTO THE SOFT GRAVEL SHOULDER. IT WAS SAFER TO RIDE INTO THE DITCH SO THAT IS WHAT I DID. JUST AFTER COMING UP ON THE OTHER SIDE OF THE DITCH THE FRONT FORK BROKE ON A SMALL BUMP LAUNCHING ME THROUGH THE AIR, AND TOPPLING THE BIKE BEHIND ME. I WAS PROBABLY GOING ABOUT 40MPH AT THE TIME OF THE FAILURE. I DISLOCATED MY SHOULDER AND TORE SEVERAL TENDONS IN THE INCIDENT. THE MOTORCYCLE IS A BMW F650 GS DAKAR. THE FAILURE IS VERY SIMILAR TO... CASE: IVOQ-2002 BMW MOTORCYCLE CASE NUMBER: 28597. *TR

1 of 1 21/10/08 10:54 AM