



## **OFFICE OF DEFECTS INVESTIGATION (ODI)**

## **Complaints - Search Results**

1 Record(s) Displayed.

Report Date: October 2, 2009 at 06:08 AM

ODI Numbers Searched: 10285955

Make: BMW Model: F650GS Year: 2001

Manufacturer: BAYERISCHE MOTOREN WERKE

Crash: Yes Fire: No Number of Injuries: 0

ODI ID Number: 10285955 Number of Deaths: 0

Date of Failure: June 30, 2003

VIN: WB10182A21Z...

Component: SUSPENSION:FRONT

Summary:

2001 BMW F650GS FRONT FORK FAILURE - WHILE RIDING ON SMOOTH ASPHALT MY MOTORCYCLE SUFFERED A CATASTROPHIC FORK FAILURE DURING DECELERATION - BRAKING CAUSING THE AXLE TO SEPARATE FROM THE FORK AND CAUSING A ONE VEHICLE COLLISION RIDING IT INTO THE ESPLANADE - WHERE THE AXLE RETAINER BOLT SECURES THE AXLE. REPAIRS COMPLETED - REPLACE BOTH UPPER FORK TUBES / RIGHT SIDE LOWER AND REBUILD COST \$800 CDN OLD LOWER - FAILURE IS AVAILABLE

1 of 1 2/10/09 8:08 PM